



30553 Wixom Road, Suite 500 • Wixom, Michigan 48393 • Voice: 248.926.3800 • Fax: 248.926.3838
 12330 Perry Highway, Suite 240 • Wexford, PA 15090 • Voice: 412.463.6576

Environmental Services, Inc.

May 5, 2014

Mr. Barry Ellentuck
 President
 ADR Consultants, LLC
 6364 Ramwyck Court, Suite C
 West Bloomfield, MI 48322

**RE: HAZARDOUS MATERIALS SURVEY REPORT
 HARDEST HIT FUND PROPERTIES
 674 ALGONQUIN; PARCEL #21046809
 DETROIT, MICHIGAN
 PERFORMANCE PROJECT #143186-H**

Dear Mr. Ellentuck:

In accordance with your request, Performance Environmental Services, Inc. conducted a hazardous material survey of the property located at 674 Algonquin in Detroit, Michigan. To complete the survey, an EPA certified and Michigan Department of Licensing and Regulatory Affairs (LARA) accredited Asbestos Building Inspector performed an on-site investigation of the property and collected samples suspected of containing asbestos in accessible areas within the study area. The purpose of the survey was to note the presence of materials that have the potential to become hazardous during demolition and to locate and to identify building materials suspected of containing asbestos. The suspected asbestos-containing samples were analyzed at a National Voluntary Laboratory Accreditation Program (NVLAP) accredited laboratory using Polarized Light Microscopy (PLM).

As a result of our survey and laboratory analysis, ***no asbestos-containing materials were identified, however the following hazardous materials were found:***


Hazardous Material		
Material	~ Quantity	Location
Tire	1	Living room
Oil pan	1	Garage

Attached, please find the Hazardous Materials Survey Report, which includes the complete laboratory data and the chain of custody records. If there are any questions or comments concerning this report or our recommendations, please do not hesitate to contact us.


Mr. Barry Ellentuck
Hazardous Material Survey Report
HHF – 674 Algonquin; Parcel #21046809
Detroit, Michigan
May 5, 2014
Page 2

Respectfully,

PERFORMANCE ENVIRONMENTAL SERVICES, INC.



Jeffrey S. Gross
Senior Project Manager



Dennis A. Wood
Senior Project Manager

JSG/DAW:hr

Attachments

TABLE OF CONTENTS

1.0	INTRODUCTION.....	1
2.0	SCOPE OF WORK.....	1
3.0	SURVEY OVERVIEW AND FINDINGS.....	1
4.0	SUMMARY AND RECOMMENDATIONS	4

APPENDICES

APPENDIX 1.....	SURVEY DOCUMENTATION
APPENDIX 2	SITE PHOTO

1.0 INTRODUCTION

ADR Consultants, LLC (ADR) contracted Performance Environmental Services, Inc. (*Performance*) to conduct a hazardous materials survey of the property at 674 Algonquin in Detroit, Michigan. The purpose of the survey was to note the presence of materials that have the potential to become hazardous during demolition and to locate and identify building materials suspected of containing asbestos. *Performance* representative Mr. Jonathan Burtraw (Accreditation #A9816) conducted the on-site survey and sample collection activities on April 29, 2014.

2.0 SCOPE OF WORK

ADR provided locations for the scope of work and the subsequent survey areas. An EPA certified and Michigan Department of Licensing and Regulatory Affairs (LARA) accredited Asbestos Building Inspector performed the survey to note the presence of materials that have the potential to become hazardous during demolition and to locate and sample materials suspected of containing asbestos. *Performance* also provided project review, report preparation and consultation services during the course of this project.

As part of this study, *Performance* completed the following:

- 1) Conducted a survey of accessible areas to note the presence of materials that have the potential to become hazardous during demolition and to locate building materials suspected of containing asbestos;
- 2) Collected bulk material samples for subsequent analysis by Polarized Light Microscopy (PLM); and,
- 3) Submitted bulk samples collected during this survey to a National Voluntary Laboratory Accreditation Program (NVLAP) accredited laboratory for PLM analysis.

Performance assembled the information collected during the study in this report, which details the laboratory results and locations of sampled materials.

3.0 SURVEY OVERVIEW AND FINDINGS

3.1 SUSPECTED HAZARDOUS AND ASBESTOS-CONTAINING BUILDING MATERIALS

As a result of our survey, *Performance* observed equipment that contained materials that may become hazardous during demolition. The potentially hazardous materials were documented as follows:

Hazardous Material		
Material	~ Quantity	Location
Tire	1	Living room
Oil pan	1	Garage

Performance also observed ten (10) types of material suspected of containing asbestos. The suspect materials were classified into homogeneous areas. A homogeneous area (HA) is a building material that appears similar in terms of color, texture, and apparent date of application. The materials were assigned HA numbers 1 through 10, and were compiled as follows:

- 1) 12" x 12" Floor tile (brown) and yellow mastic;
- 2) 2'x 4' Lay-in ceiling tile (white, textured);
- 3) 1'x 1' Splined ceiling tile (white, wormhole and pinhole);
- 4) Wall panel adhesive (brown);
- 5) 12" x 12" Floor tile (brown, faux wood pattern) and yellow mastic;
- 6) 12" x 12" Floor tile (off-white, square pattern) and black mastic;
- 7) Textured paint (white, peak and valley);
- 8) Hard plaster (off-white);
- 9) Drywall and joint compound; and,
- 10) Window glaze (white and tan).

3.2 IDENTIFIED ASBESTOS-CONTAINING BUILDING MATERIALS

Performance collected twenty-four (24) bulk material samples of the identified homogeneous areas and submitted them to an NVLAP-accredited laboratory for PLM analysis. As the laboratory results indicate, **no asbestos was detected in any of the materials sampled.**

Refer to the attached Appendix for the complete laboratory data and the Chain of Custody records.

3.3 DISCUSSION

3.3.1 Asbestos Control and Management

Renovation and demolition activities, as well as some maintenance activities have the potential to disturb materials and release asbestos fibers into the environment.

EPA:

The Environmental Protection Agency (EPA), under the National Emission Standards for Hazardous Air Pollutants (NESHAPS), requires notification and procedures for emissions control depending on whether the asbestos material in question falls into the definition of "Regulated Asbestos-Containing Material" (RACM). NESHAPS defines RACM as:

- (a) Friable asbestos material,
- (b) Category I nonfriable ACM that has become friable,
- (c) Category I nonfriable ACM that will be or has been subjected to sanding, grinding, cutting, or abrading, or
- (d) Category II nonfriable ACM that has a high probability of becoming or has become crumbled, pulverized, or reduced to powder by the forces expected to act on the material in the course of demolition or renovation operations.

The proceeding items summarize basic requirements for demolition and renovation projects according to NESHAPS:

(1) In a facility being **demolished**, notification requirements and procedures for asbestos emission control apply if the combined amount of RACM is (i) At least 260 linear feet on pipes or at least 160 square feet on other facility components, or (ii) At least 35 cubic feet off facility components where the length or area could not be measured previously.

(2) In a facility being **demolished**, only the notification requirements apply, if the combined amount of RACM is (i) *Less than* 260 linear feet on pipes and less than 160 square feet on other facility components, and (ii) *Less than* 35 cubic feet off facility components where the length or area could not be measured previously or there is no asbestos.

(3) If the facility is being **demolished** under an order of a State or local government agency issued because the facility is structurally unsound and in danger of imminent collapse, specific requirements apply (see NESHAPS for details).

(4) If the facility is being **renovated**, notification requirements and procedures for asbestos emission control apply if the combined amount of RACM to be stripped, removed, dislodged, cut, drilled, or similarly disturbed is (i) At least 260 linear feet on pipes or at least 160 square feet on other facility components, or (ii) At least 35 cubic feet off facility components where the length or area could not be measured previously.

Michigan LARA:

According to the Michigan Department of Licensing and Regulatory Affairs (LARA), in a facility where demolition, renovation or encapsulation is to occur, notification requirements and procedures for asbestos emission control apply if the combined amount of RACM is at least 10 linear feet on pipes or at least 15 square feet on other facility components.

3.3.2 Survey Limitations and Miscellaneous Field Notes

Performance noted several items that may contain materials that can become hazardous during demolition. Refer to hazardous materials table in section 3.1 of this report.

The scope of work for this project did not include the sampling of ceramic tile or wood flooring. Potential asbestos-containing materials associated with ceramic tile or wood flooring including underlying flooring materials and/or mastic.

The scope of work for this project did not include the sampling of complete roofing systems unless the material was in severely damaged condition and may become friable during demolition. Potential asbestos-containing materials associated with roofing systems include but are not limited to flashings and membranes.

Remodeling and renovations within buildings often result in asbestos-containing flooring products (flooring and mastics) being covered with non-asbestos flooring products. Although every attempt is made to properly delineate flooring types during survey

activities, due to the limited destructive nature of sampling *Performance* assumes asbestos-containing materials may be present below sampled flooring in areas not inspected. It is imperative that if flooring finishes in an area differ from areas where samples were collected, additional samples are collected and analyzed of the newly uncovered material before disturbance occurs.

Performance did not sample any system that presented a health and safety hazard to the inspector such as energized electrical systems, elevator components, active mechanical systems, or within confined spaces.

Performance has prepared this report for the express use of its clients and their approved agents. Although some of the information included in this report or in portions of this report may be required to be included in notifications to various parties, this report is not intended to be used as an asbestos specification or work plan.

This report is based upon conditions observed at the property at the time of the inspection. This report does not intend to identify all hazards or to indicate that other hazards do not exist at the project site. Environmental conditions and regulations are subject to constant change and reinterpretation.

4.0 SUMMARY AND RECOMMENDATIONS

Hazardous Materials:

The various items listed in the hazardous materials table in section 3.1 of this report contain materials that can become hazardous during demolition. ***Performance* recommends removing the hazardous materials before demolition and properly disposing of the materials according to the applicable laws and regulations.**

The scope of work for this project did not include testing for lead-based paint. *Performance* did note that peeling paint was found throughout the structure. Although current regulations do not require removal of lead-based paint prior to demolition, ***Performance* recommends testing for airborne lead during demolition activities** to ensure that worker exposure does not exceed permissible exposure limits. Furthermore, *Performance* recommends avoiding activities that may increase worker exposure to potential airborne lead. Activities that can increase worker exposure include sanding, grinding, cutting, or abrading lead-based painted materials.

Asbestos-Containing Materials

There were no asbestos-containing materials located during this survey.

APPENDIX 1

SURVEY DOCUMENTATION

CONTENTS

-
- ▶ CERTIFICATES OF
LABORATORY ANALYSIS
 - ▶ CHAIN OF CUSTODY RECORDS



Certificate of Laboratory Analysis

Test Method, Polarized Light Microscopy (PLM)

Project: 674 Algonquin
Project #:143186-H

Report To:

Mr. Jonathan Burtraw
Performance Environmental Services, Inc.
30553 Wixom Road, Ste. 500
Wixom, MI 48393

ARI Report # 14-51985
Date Collected: 04/29/14
Date Received: 04/30/14
Date Analyzed: 04/30/14
Date Reported: 04/30/14

Sample Information	Asbestos Type/Percent	Non-Asbestos
Lab ID #: 51985 - 1 Cust. #: 1-01 Material: 12x12 Floor Tile Location: Kitchen Appearance: brown,nonfibrous,homogenous Layer: 1 of 2	Asbestos Present: NO No Asbestos Observed	Other - 100%
Lab ID #: 51985 - 1a Cust. #: 1-01 Material: Mastic Location: Kitchen Appearance: clear,nonfibrous,homogenous Layer: 2 of 2	Asbestos Present: NO No Asbestos Observed	Other - 100%
Lab ID #: 51985 - 2 Cust. #: 1-02 Material: 12x12 Floor Tile Location: Kitchen Appearance: brown,nonfibrous,homogenous Layer: 1 of 2	Asbestos Present: NO No Asbestos Observed	Other - 100%

For Layered Samples, each component will be analyzed and reported separately.

Robert T. Letarte Jr., Laboratory Director

Test Method EPA 600/R-93/116 was used to analyze the above samples. Matrix interference and/or resolution limits may yield false/negative results in certain circumstances. Suspect floor tiles containing <1% should be tested with SEM or TEM. This certificate of analysis relates only to the samples tested and to insure the integrity of the results, may only be reproduced in full. This certificate may not be used by the customer to claim product endorsement by NVLAP or any agency of the US Government. APEX Research Inc. is not responsible for the accuracy of the results for layered samples or samples comprising multiple materials. Liability limited to cost of analysis.



NVLAP Lab Code 102118-0



Certificate of Laboratory Analysis

Test Method, Polarized Light Microscopy (PLM)

Project: 674 Algonquin
Project #:143186-H

Report To:

Mr. Jonathan Burtraw
Performance Environmental Services, Inc.
30553 Wixom Road, Ste. 500
Wixom, MI 48393

ARI Report # 14-51985
Date Collected: 04/29/14
Date Received: 04/30/14
Date Analyzed: 04/30/14
Date Reported: 04/30/14

Sample Information	Asbestos Type/Percent	Non-Asbestos
Lab ID #: 51985 - 2a Cust. #: 1-02 Material: Mastic Location: Kitchen Appearance: clear,nonfibrous,homogenous Layer: 2 of 2	Asbestos Present: NO No Asbestos Observed	Other - 100%
Lab ID #: 51985 - 3 Cust. #: 2-01 Material: 2x4 Ceiling Tile Location: 2nd Fl SW Bedrm Appearance: brown,fibrous,homogenous Layer: 1 of 1	Asbestos Present: NO No Asbestos Observed	Cellulose - 90% Other - 10%
Lab ID #: 51985 - 4 Cust. #: 2-02 Material: 2x4 Ceiling Tile Location: 2nd Fl SW Bedrm Appearance: brown,fibrous,homogenous Layer: 1 of 1	Asbestos Present: NO No Asbestos Observed	Cellulose - 90% Other - 10%

For Layered Samples, each component will be analyzed and reported separately.

Robert T. Letarte Jr., Laboratory Director

Test Method EPA 600/R-93/116 was used to analyze the above samples. Matrix interference and/or resolution limits may yield false/negative results in certain circumstances. Suspect floor tiles containing <1% should be tested with SEM or TEM. This certificate of analysis relates only to the samples tested and to insure the integrity of the results, may only be reproduced in full. This certificate may not be used by the customer to claim product endorsement by NVLAP or any agency of the US Government. APEX Research Inc. is not responsible for the accuracy of the results for layered samples or samples comprising multiple materials. Liability limited to cost of analysis.



NVLAP Lab Code 102118-0



Certificate of Laboratory Analysis

Test Method, Polarized Light Microscopy (PLM)

Project: 674 Algonquin
Project #:143186-H


Report To:

Mr. Jonathan Burtraw
Performance Environmental Services, Inc.
30553 Wixom Road, Ste. 500
Wixom, MI 48393

ARI Report # 14-51985
Date Collected: 04/29/14
Date Received: 04/30/14
Date Analyzed: 04/30/14
Date Reported: 04/30/14

Sample Information	Asbestos Type/Percent	Non-Asbestos
Lab ID #: 51985 - 5 Cust. #: 3-01 Material: 1x1 Ceiling Tile Location: Basement Appearance: brown, fibrous, homogenous Layer: 1 of 1	Asbestos Present: NO No Asbestos Observed	Cellulose - 90% Other - 10%
Lab ID #: 51985 - 6 Cust. #: 3-02 Material: 1x1 Ceiling Tile Location: Basement Appearance: brown, fibrous, homogenous Layer: 1 of 1	Asbestos Present: NO No Asbestos Observed	Cellulose - 90% Other - 10%
Lab ID #: 51985 - 7 Cust. #: 4-01 Material: Wall Panel Adhesive Location: 2nd Fl. Bathroom Appearance: yellow, nonfibrous, homogenous Layer: 1 of 1	Asbestos Present: NO No Asbestos Observed	Other - 100%

For Layered Samples, each component will be analyzed and reported separately.


 Robert T. Letarte Jr., Laboratory Director

Test Method EPA 600/R-93/116 was used to analyze the above samples. Matrix interference and/or resolution limits may yield false/negative results in certain circumstances. Suspect floor tiles containing <1% should be tested with SEM or TEM. This certificate of analysis relates only to the samples tested and to insure the integrity of the results, may only be reproduced in full. This certificate may not be used by the customer to claim product endorsement by NVLAP or any agency of the US Government. APEX Research Inc. is not responsible for the accuracy of the results for layered samples or samples comprising multiple materials. Liability limited to cost of analysis.



NVLAP Lab Code 102118-0



Certificate of Laboratory Analysis

Test Method, Polarized Light Microscopy (PLM)

Project: 674 Algonquin
Project #: 143186-H


Report To:

Mr. Jonathan Burtraw
Performance Environmental Services, Inc.
30553 Wixom Road, Ste. 500
Wixom, MI 48393

ARI Report # 14-51985
Date Collected: 04/29/14
Date Received: 04/30/14
Date Analyzed: 04/30/14
Date Reported: 04/30/14

Sample Information	Asbestos Type/Percent	Non-Asbestos
Lab ID #: 51985 - 8 Cust. #: 4-02 Material: Wall Panel Adhesive Location: 2nd Fl. Bathroom Appearance: yellow, nonfibrous, homogenous Layer: 1 of 1	Asbestos Present: NO No Asbestos Observed	Other - 100%
Lab ID #: 51985 - 9 Cust. #: 5-01 Material: 12x12 Floor Tile Location: Basement Stair Appearance: brown, fibrous, homogenous Layer: 1 of 2	Asbestos Present: NO No Asbestos Observed	Cellulose - 2% Other - 98%
Lab ID #: 51985 - 9a Cust. #: 5-01 Material: Mastic Location: Basement Stair Appearance: clear, nonfibrous, homogenous Layer: 2 of 2	Asbestos Present: NO No Asbestos Observed	Other - 100%

For Layered Samples, each component will be analyzed and reported separately.


 Robert T. Letarte Jr., Laboratory Director

Test Method EPA 600/R-93/116 was used to analyze the above samples. Matrix interference and/or resolution limits may yield false/negative results in certain circumstances. Suspect floor tiles containing <1% should be tested with SEM or TEM. This certificate of analysis relates only to the samples tested and to insure the integrity of the results, may only be reproduced in full. This certificate may not be used by the customer to claim product endorsement by NVLAP or any agency of the US Government. APEX Research Inc. is not responsible for the accuracy of the results for layered samples or samples comprising multiple materials. Liability limited to cost of analysis.



NVLAP Lab Code 102118-0



Certificate of Laboratory Analysis

Test Method, Polarized Light Microscopy (PLM)

Project: 674 Algonquin
Project #: 143186-H


Report To:

Mr. Jonathan Burtraw
Performance Environmental Services, Inc.
30553 Wixom Road, Ste. 500
Wixom, MI 48393

ARI Report # 14-51985
Date Collected: 04/29/14
Date Received: 04/30/14
Date Analyzed: 04/30/14
Date Reported: 04/30/14

Sample Information	Asbestos Type/Percent	Non-Asbestos
Lab ID #: 51985 - 10 Cust. #: 5-02 Material: 12x12 Floor Tile Location: Basement Stair Appearance: brown, fibrous, homogenous Layer: 1 of 2	Asbestos Present: NO No Asbestos Observed	Cellulose - 2% Other - 98%
Lab ID #: 51985 - 10a Cust. #: 5-02 Material: Glue Location: Basement Stair Appearance: clear, nonfibrous, homogenous Layer: 2 of 2	Asbestos Present: NO No Asbestos Observed	Other - 100%
Lab ID #: 51985 - 11 Cust. #: 6-01 Material: 12x12 Floor Tile Location: 2nd Fl. Bathroom Appearance: white, nonfibrous, homogenous Layer: 1 of 2	Asbestos Present: NO No Asbestos Observed	Other - 100%

For Layered Samples, each component will be analyzed and reported separately.


 Robert T. Letarte Jr., Laboratory Director

Test Method EPA 600/R-93/116 was used to analyze the above samples. Matrix interference and/or resolution limits may yield false/negative results in certain circumstances. Suspect floor tiles containing <1% should be tested with SEM or TEM. This certificate of analysis relates only to the samples tested and to insure the integrity of the results, may only be reproduced in full. This certificate may not be used by the customer to claim product endorsement by NVLAP or any agency of the US Government. APEX Research Inc. is not responsible for the accuracy of the results for layered samples or samples comprising multiple materials. Liability limited to cost of analysis.



NVLAP Lab Code 102118-0



Certificate of Laboratory Analysis

Test Method, Polarized Light Microscopy (PLM)

Project: 674 Algonquin
Project #:143186-H

Report To:

Mr. Jonathan Burtraw
Performance Environmental Services, Inc.
30553 Wixom Road, Ste. 500
Wixom, MI 48393

ARI Report # 14-51985
Date Collected: 04/29/14
Date Received: 04/30/14
Date Analyzed: 04/30/14
Date Reported: 04/30/14

Sample Information	Asbestos Type/Percent	Non-Asbestos
Lab ID #: 51985 - 11a Cust. #: 6-01 Material: Mastic Location: 2nd Fl. Bathroom Appearance: black,nonfibrous,homogenous Layer: 2 of 2	Asbestos Present: NO No Asbestos Observed	Other - 100%
Lab ID #: 51985 - 12 Cust. #: 6-02 Material: 12x12 Floor Tile Location: 2nd Fl. Bathroom Appearance: white,nonfibrous,homogenous Layer: 1 of 2	Asbestos Present: NO No Asbestos Observed	Other - 100%
Lab ID #: 51985 - 12a Cust. #: 6-02 Material: Mastic Location: 2nd Fl. Bathroom Appearance: black,nonfibrous,homogenous Layer: 2 of 2	Asbestos Present: NO No Asbestos Observed	Other - 100%

For Layered Samples, each component will be analyzed and reported separately.

Robert T. Letarte Jr., Laboratory Director

Test Method EPA 600/R-93/116 was used to analyze the above samples. Matrix interference and/or resolution limits may yield false/negative results in certain circumstances. Suspect floor tiles containing <1% should be tested with SEM or TEM. This certificate of analysis relates only to the samples tested and to insure the integrity of the results, may only be reproduced in full. This certificate may not be used by the customer to claim product endorsement by NVLAP or any agency of the US Government. APEX Research Inc. is not responsible for the accuracy of the results for layered samples or samples comprising multiple materials. Liability limited to cost of analysis.



NVLAP Lab Code 102118-0



Certificate of Laboratory Analysis

Test Method, Polarized Light Microscopy (PLM)

Project: 674 Algonquin
Project #:143186-H


Report To:

Mr. Jonathan Burtraw
Performance Environmental Services, Inc.
30553 Wixom Road, Ste. 500
Wixom, MI 48393

ARI Report # 14-51985
Date Collected: 04/29/14
Date Received: 04/30/14
Date Analyzed: 04/30/14
Date Reported: 04/30/14

Sample Information	Asbestos Type/Percent	Non-Asbestos
Lab ID #: 51985 - 13 Cust. #: 7-01 Material: Textured Paint Location: Living Room Appearance: white,nonfibrous,homogenous Layer: 1 of 1	Asbestos Present: NO No Asbestos Observed	Other - 100%
Lab ID #: 51985 - 14 Cust. #: 7-02 Material: Textured Paint Location: Living Room Appearance: white,nonfibrous,homogenous Layer: 1 of 1	Asbestos Present: NO No Asbestos Observed	Other - 100%
Lab ID #: 51985 - 15 Cust. #: 7-03 Material: Textured Paint Location: Dining Room Appearance: white,nonfibrous,homogenous Layer: 1 of 1	Asbestos Present: NO No Asbestos Observed	Other - 100%

For Layered Samples, each component will be analyzed and reported separately.


 Robert T. Letarte Jr., Laboratory Director

Test Method EPA 600/R-93/116 was used to analyze the above samples. Matrix interference and/or resolution limits may yield false/negative results in certain circumstances. Suspect floor tiles containing <1% should be tested with SEM or TEM. This certificate of analysis relates only to the samples tested and to insure the integrity of the results, may only be reproduced in full. This certificate may not be used by the customer to claim product endorsement by NVLAP or any agency of the US Government. APEX Research Inc. is not responsible for the accuracy of the results for layered samples or samples comprising multiple materials. Liability limited to cost of analysis.



NVLAP Lab Code 102118-0



Certificate of Laboratory Analysis

Test Method, Polarized Light Microscopy (PLM)

Project: 674 Algonquin
Project #: 143186-H


Report To:

Mr. Jonathan Burtraw
Performance Environmental Services, Inc.
30553 Wixom Road, Ste. 500
Wixom, MI 48393

ARI Report # 14-51985
Date Collected: 04/29/14
Date Received: 04/30/14
Date Analyzed: 04/30/14
Date Reported: 04/30/14

Sample Information	Asbestos Type/Percent	Non-Asbestos
Lab ID #: 51985 - 16 Cust. #: 8-01 Material: Hard Plaster Location: Kitchen Appearance: white, nonfibrous, homogenous Layer: 1 of 2	Asbestos Present: NO No Asbestos Observed	Other - 100%
Lab ID #: 51985 - 16a Cust. #: 8-01 Material: Mortar Location: Kitchen Appearance: white, fibrous, homogenous Layer: 2 of 2	Asbestos Present: NO No Asbestos Observed	Hair - 5% Other - 95%
Lab ID #: 51985 - 17 Cust. #: 8-02 Material: Hard Plaster Location: Dining Room Appearance: white, nonfibrous, homogenous Layer: 1 of 2	Asbestos Present: NO No Asbestos Observed	Other - 100%

For Layered Samples, each component will be analyzed and reported separately.


 Robert T. Letarte Jr., Laboratory Director

Test Method EPA 600/R-93/116 was used to analyze the above samples. Matrix interference and/or resolution limits may yield false/negative results in certain circumstances. Suspect floor tiles containing <1% should be tested with SEM or TEM. This certificate of analysis relates only to the samples tested and to insure the integrity of the results, may only be reproduced in full. This certificate may not be used by the customer to claim product endorsement by NVLAP or any agency of the US Government. APEX Research Inc. is not responsible for the accuracy of the results for layered samples or samples comprising multiple materials. Liability limited to cost of analysis.



NVLAP Lab Code 102118-0



Certificate of Laboratory Analysis

Test Method, Polarized Light Microscopy (PLM)

Project: 674 Algonquin
Project #: 143186-H


Report To:

Mr. Jonathan Burtraw
Performance Environmental Services, Inc.
30553 Wixom Road, Ste. 500
Wixom, MI 48393

ARI Report # 14-51985
Date Collected: 04/29/14
Date Received: 04/30/14
Date Analyzed: 04/30/14
Date Reported: 04/30/14

Sample Information	Asbestos Type/Percent	Non-Asbestos
Lab ID #: 51985 - 17a Cust. #: 8-02 Material: Mortar Location: Dining Room Appearance: grey, fibrous, homogenous Layer: 2 of 2	Asbestos Present: NO Chrysotile - Trace POINT COUNT RESULT	Other - 100%
Lab ID #: 51985 - 18 Cust. #: 8-03 Material: Hard Plaster Location: Living Room Appearance: white, nonfibrous, homogenous Layer: 1 of 2	Asbestos Present: NO No Asbestos Observed	Other - 100%
Lab ID #: 51985 - 18a Cust. #: 8-03 Material: Mortar Location: Living Room Appearance: grey, fibrous, homogenous Layer: 2 of 2	Asbestos Present: NO Chrysotile - 0.25% POINT COUNT RESULT	Other - 99.75%

For Layered Samples, each component will be analyzed and reported separately.


 Robert T. Letarte Jr., Laboratory Director

Test Method EPA 600/R-93/116 was used to analyze the above samples. Matrix interference and/or resolution limits may yield false/negative results in certain circumstances. Suspect floor tiles containing <1% should be tested with SEM or TEM. This certificate of analysis relates only to the samples tested and to insure the integrity of the results, may only be reproduced in full. This certificate may not be used by the customer to claim product endorsement by NVLAP or any agency of the US Government. APEX Research Inc. is not responsible for the accuracy of the results for layered samples or samples comprising multiple materials. Liability limited to cost of analysis.



NVLAP Lab Code 102118-0



Certificate of Laboratory Analysis

Test Method, Polarized Light Microscopy (PLM)

Project: 674 Algonquin
Project #:143186-H


Report To:

Mr. Jonathan Burtraw
Performance Environmental Services, Inc.
30553 Wixom Road, Ste. 500
Wixom, MI 48393

ARI Report # 14-51985
Date Collected: 04/29/14
Date Received: 04/30/14
Date Analyzed: 04/30/14
Date Reported: 04/30/14

Sample Information	Asbestos Type/Percent	Non-Asbestos
Lab ID #: 51985 - 19 Cust. #: 8-04 Material: Hard Plaster Location: Living Room Appearance: white,nonfibrous,homogenous Layer: 1 of 2	Asbestos Present: NO No Asbestos Observed	Other - 100%
Lab ID #: 51985 - 19a Cust. #: 8-04 Material: Mortar Location: Living Room Appearance: grey,fibrous,homogenous Layer: 2 of 2	Asbestos Present: NO Chrysotile - Trace POINT COUNT RESULT	Other - 100%
Lab ID #: 51985 - 20 Cust. #: 8-05 Material: Hard Plaster Location: 2nd Fl. NW Bedrm Appearance: white,nonfibrous,homogenous Layer: 1 of 2	Asbestos Present: NO No Asbestos Observed	Other - 100%

For Layered Samples, each component will be analyzed and reported separately.


 Robert T. Letarte Jr., Laboratory Director

Test Method EPA 600/R-93/116 was used to analyze the above samples. Matrix interference and/or resolution limits may yield false/negative results in certain circumstances. Suspect floor tiles containing <1% should be tested with SEM or TEM. This certificate of analysis relates only to the samples tested and to insure the integrity of the results, may only be reproduced in full. This certificate may not be used by the customer to claim product endorsement by NVLAP or any agency of the US Government. APEX Research Inc. is not responsible for the accuracy of the results for layered samples or samples comprising multiple materials. Liability limited to cost of analysis.



NVLAP Lab Code 102118-0



Certificate of Laboratory Analysis

Test Method, Polarized Light Microscopy (PLM)

Project: 674 Algonquin
Project #:143186-H


Report To:

Mr. Jonathan Burtraw
Performance Environmental Services, Inc.
30553 Wixom Road, Ste. 500
Wixom, MI 48393

ARI Report # 14-51985
Date Collected: 04/29/14
Date Received: 04/30/14
Date Analyzed: 04/30/14
Date Reported: 04/30/14

Sample Information	Asbestos Type/Percent	Non-Asbestos
Lab ID #: 51985 - 20a Cust. #: 8-05 Material: Mortar Location: 2nd Fl. NW Bedrm Appearance: grey, fibrous, homogenous Layer: 2 of 2	Asbestos Present: NO Chrysotile - Trace POINT COUNT RESULT	Other - 100%
Lab ID #: 51985 - 21 Cust. #: 9-01 Material: Drywall Location: Basement Appearance: white, fibrous, homogenous Layer: 1 of 2	Asbestos Present: NO No Asbestos Observed	Cellulose - 20% Other - 80%
Lab ID #: 51985 - 21a Cust. #: 9-01 Material: Joint Compound Location: Basement Appearance: white, nonfibrous, homogenous Layer: 2 of 2	Asbestos Present: NO No Asbestos Observed	Other - 100%

For Layered Samples, each component will be analyzed and reported separately.


 Robert T. Letarte Jr., Laboratory Director

Test Method EPA 600/R-93/116 was used to analyze the above samples. Matrix interference and/or resolution limits may yield false/negative results in certain circumstances. Suspect floor tiles containing <1% should be tested with SEM or TEM. This certificate of analysis relates only to the samples tested and to insure the integrity of the results, may only be reproduced in full. This certificate may not be used by the customer to claim product endorsement by NVLAP or any agency of the US Government. APEX Research Inc. is not responsible for the accuracy of the results for layered samples or samples comprising multiple materials. Liability limited to cost of analysis.



NVLAP Lab Code 102118-0



Certificate of Laboratory Analysis

Test Method, Polarized Light Microscopy (PLM)

Project: 674 Algonquin
Project #:143186-H


Report To:

Mr. Jonathan Burtraw
Performance Environmental Services, Inc.
30553 Wixom Road, Ste. 500
Wixom, MI 48393

ARI Report # 14-51985
Date Collected: 04/29/14
Date Received: 04/30/14
Date Analyzed: 04/30/14
Date Reported: 04/30/14

Sample Information	Asbestos Type/Percent	Non-Asbestos
Lab ID #: 51985 - 22 Cust. #: 9-02 Material: Drywall Location: Basement Appearance: white, fibrous, homogenous Layer: 1 of 2	Asbestos Present: NO No Asbestos Observed	Cellulose - 20% Other - 80%
Lab ID #: 51985 - 22a Cust. #: 9-02 Material: Joint Compound Location: Basement Appearance: white, nonfibrous, homogenous Layer: 2 of 2	Asbestos Present: NO No Asbestos Observed	Other - 100%
Lab ID #: 51985 - 23 Cust. #: 10-01 Material: Window Glaze Location: 1st Fl. N. Window Appearance: beige, nonfibrous, homogenous Layer: 1 of 1	Asbestos Present: NO No Asbestos Observed	Other - 100%

For Layered Samples, each component will be analyzed and reported separately.


 Robert T. Letarte Jr., Laboratory Director

Test Method EPA 600/R-93/116 was used to analyze the above samples. Matrix interference and/or resolution limits may yield false/negative results in certain circumstances. Suspect floor tiles containing <1% should be tested with SEM or TEM. This certificate of analysis relates only to the samples tested and to insure the integrity of the results, may only be reproduced in full. This certificate may not be used by the customer to claim product endorsement by NVLAP or any agency of the US Government. APEX Research Inc. is not responsible for the accuracy of the results for layered samples or samples comprising multiple materials. Liability limited to cost of analysis.



NVLAP Lab Code 102118-0



Certificate of Laboratory Analysis

Test Method, Polarized Light Microscopy (PLM)

Project: 674 Algonquin
Project #:143186-H

Report To:

Mr. Jonathan Burtraw
Performance Environmental Services, Inc.
30553 Wixom Road, Ste. 500
Wixom, MI 48393

ARI Report # 14-51985
Date Collected: 04/29/14
Date Received: 04/30/14
Date Analyzed: 04/30/14
Date Reported: 04/30/14

Sample Information**Asbestos Type/Percent****Non-Asbestos**

Lab ID #: 51985 - 24 Cust. #: 10-02 Material: Window Glaze Location: 1st fl. S. Window Appearance: beige, nonfibrous, homogenous Layer: 1 of 1	Asbestos Present: NO No Asbestos Observed	Other - 100%
Lab ID #: Cust. #: Material: Location: Appearance: Layer: of	Asbestos Present:	
Lab ID #: Cust. #: Material: Location: Appearance: Layer: of	Asbestos Present:	

For Layered Samples, each component will be analyzed and reported separately.

Robert T. Letarte Jr., Laboratory Director

Test Method EPA 600/R-93/116 was used to analyze the above samples. Matrix interference and/or resolution limits may yield false/negative results in certain circumstances. Suspect floor tiles containing <1% should be tested with SEM or TEM. This certificate of analysis relates only to the samples tested and to insure the integrity of the results, may only be reproduced in full. This certificate may not be used by the customer to claim product endorsement by NVLAP or any agency of the US Government. APEX Research Inc. is not responsible for the accuracy of the results for layered samples or samples comprising multiple materials. Liability limited to cost of analysis.



NVLAP Lab Code 102118-0

Performance Environmental Services, Inc.

51985

PLM LABORATORY CHAIN OF CUSTODY

PROJECT #: 143186-N

CLIENT: ADR Consultants, LLC

DATE COLLECTED: 04/29/14

PROJECT: 674 Alisonwood

LOCATION: Detroit, MI

TECHNICIAN 1: Jonathan Burtraw

TECHNICIAN 2:

NOTIFY RESULTS VIA:		SAMPLES RELINQUISHED BY:		TURNAROUND TIME:	DATE:	SAMPLES ACCEPTED BY:	DATE:
HA NUMBER	SAMPLE NUMBER	MATERIAL DESCRIPTION	labdata@perform-env.com	SAMPLING LOCATION	APEX RESEARCH	TEST HA LAYERS UNTIL POSITIVE:	COMMENTS/RESULTS
1	1-01	12" x 12" Floor tile (brown and (clear) mark)	↓	Kitchen	04/29/14	RECEIVED	
2	1-02	2' x 4' lay-in ceiling tile (white, textured)	↓	2nd Floor Southwest Bedroom	APR 30 2014		
3	2-01	1' x 1' spindled ceiling tile (white, wood-grain and pinkish)	↓	Bedroom			
3	3-01	Wall panel adhesive (brown)	↓	Bedroom			
4	3-02			2nd Floor: Bedroom			
4	4-01	12" x 12" Floor tile (brown, tan wood pattern) and (yellow) wood tile	↓	2nd Floor: Bedroom			
4	4-02			Bedroom			
5	5-01			Bedroom			
5	5-02			Bedroom			

Performanc# 51985

Environmental Services, In Apex

PLM LABORATORY CHAIN OF CUSTODY

PROJECT #: 143186-H CLIENT: ADR Consultants, LLC

DATE COLLECTED: 04/24/14

PROJECT: 674 Algonquin

LOCATION: Detroit, MI

TECHNICIAN 1: Jonathan Burtraw

TECHNICIAN 2:

NOTIFY RESULTS VIA:		labdata@perform-env.com	TURNAROUND TIME:	DATE:	SAMPLES RELINQUISHED BY:	DATE:	SAMPLES ACCEPTED BY:	DATE:
HA NUMBER	SAMPLE NUMBER	MATERIAL DESCRIPTION	SAMPLING LOCATION	TEM VERIFY (PLM ≤ 1%)	COMMENTS/RESULTS	Yes		
	6-01	12" x 12" floor tile (left-white, square pattern) and (black) mosaic	2nd floor Bathroom				APEX LABS UNACCEPTED	
11	6-02		↓					
12	7-01	Textured paint (white, pink and yellow)	Living Room					
13	7-02		↓					
14	7-03		Dining Room					
15	8-01	Hard plaster (left-white)	15' tube					
16	8-02		Dining Room					
17	8-03		Living Room					
18	8-04		↓					
19	8-05		2nd Floor Northwest Bedroom					
20								

Performance

Environmental Services, Inc.

S1985

PLM LABORATORY CHAIN OF CUSTODY

PROJECT #: 173186-14 CLIENT: ADR Consultants, LLC

DATE COLLECTED: 04/25/17

PROJECT: 674 Allegiance

LOCATION: Detroit, MI

TECHNICIAN 1: Jonathan Burtraw

TECHNICIAN 2:

NOTIFY RESULTS VIA:		SAMPLES RELINQUISHED BY:		TURNAROUND TIME:	DATE:	SAMPLES ACCEPTED BY:	DATE:
HA NUMBER	SAMPLE NUMBER	MATERIAL DESCRIPTION	SAMPLING LOCATION	TEST HA LAYERS UNTIL POSITIVE:	TEM VERIFY (PLM ≤ 1%)	COMMENTS/RESULTS	Yes
Jonathan Burtraw	Jonathan Burtraw	labdata@perform-env.com		Risk	04/29/17	RECEIVED	
						APR 30 2014	
9	9-01	Plywood and joint compound	Dosement				
9	9-02						
10	10-01	Window 5 (size (white and tan))	1st Floor North Window				
10	10-02		1st Floor South Window				

21
22
23
24

APPENDIX 2



SITE PHOTO

